

Staff Report City of Manhattan Beach

TO:

Honorable Mayor Tell and Members of the City Council

THROUGH: Geoff Dolan, City Manager

FROM:

Richard Gill, Parks and Recreation Director Mark Leyman, Recreation Services Manager

DATE:

February 20, 2007

SUBJECT: Request from Manhattan Beach Unified School District for Funds to Re-plaster

Begg Pool and Appropriate \$62,390 from City Council Contingency Funds.

RECOMMENDATION:

Staff recommends the approval of funds for the Manhattan Beach Unified School District (MBUSD) to Re-plaster Begg Pool and Appropriate \$62,390 from City Council Contingency Funds.

FISCAL IMPLICATION:

These repairs were not anticipated and as such were not budgeted for the current fiscal year. The joint use agreement with MBUSD requires each agency to share all capital costs equally. Since the MBUSD is asking the City to cover all costs the total amount needed from the Council contingency would be \$62,390. The current balance in the City Council Contingency Fund is \$87,000.

BACKGROUND:

Begg Pool is used year round by over 10,000 participants from the City and all physical education classes at Manhattan Beach Middle School. Due to the heavy use, the plaster and tile are in desperate need of repair. The plaster at the bottom of the pool is chipping away in large sections in numerous locations, creating an unsafe environment for participants (see attachment A). It has been over ten years since the plaster and tile have been repaired.

The Los Angeles County Health Department Inspector made a site visit to Begg pool on December 11, 2006 (attachment B). The December 11 report specifically states that the pool be re-plastered and retiled to correct the uneven, peeling and discolored surface. The MBUSD does not have the funds to share the cost of the renovation at this time. The MBUSD officially requested, at their February 7, 2007 Board Meeting (attachment C), that the City cover the entire cost of the replastering or MBUSD would be forced to close the pool.

The City of Manhattan Beach (CMB) and MBUSD have a shared use agreement for Begg Pool. Maintenance and repair costs are normally shared 50/50 between CMB and MBUSD.

Agenda Item #:	18	
-		

DISCUSSION:

Staff has met with MBUSD physical education instructors and the maintenance superintendent to discuss Begg Pool repairs. Both CMB and MBUSD staff are concerned over the liability presented by the plaster and tile conditions at Begg Pool and are willing to accept a minor rescheduling of programs to repair the pool.

If City Council approves the allocation of funds for the project, staff recommends that the pool repairs begin immediately. If approved, the repairs will begin February 21, 2007 and be completed by March 17, 2007. The spring program that normally begins March 12 will be pushed back one week. Swim participants will be notified of the pool refurbishment. If the repairs are not done immediately, the next window of opportunity will be in November as the aquatic program runs from March to November.


The MBUSD has already received three bids for the re-plastering and re-tiling of Begg Pool. Sea-Clear Pools was selected as the recommended contractor. Sea-Clear Pools was the lowest bidder for the project and has been the maintenance contractor at Begg Pool for the past ten years. MBUSD is ready to proceed immediately upon City Council approval. Both CMB and MBUSD staff will oversee the contractor doing the repairs to insure that the project is completed on time and that the repairs are done correctly.

Staff recommends that the City Council allocate \$62,390 using Council contingency funds for the re-plastering and re-tiling of Begg Pool.


ATTACHMENTS:

- A. Photographs of Begg Pool
- B. December 11, 2006 Los Angeles County Health Department Inspection Report
- C. Manhattan Beach Unified School District Board Meeting Agenda









À

SWIMMING POOL OFFICIAL INSPECTION REPORT

COUNTY OF LOS ANGELES DEPARTMENT OF HEALTH SERVICES PUBLIC HEALTH PROGRAMS – ENVIRONMENTAL HEALTH 5050 Commerce Drive, Baldwin Park, CA 91706 (626) 430-5360

Strion RIA	3030 0011		,,						
SITE ADDRESS	4/		СІТУ				DATE		
1453	15 th. 51	MAK	12/11/06						
SITE NAME		OWNER			SITE	7	SUB		
					862	9	01		
MAILING ADDRESS		CITY	POOL TYPE	ELE	Ci,	PH			
			Pool	3606	1.0	7. 1			

MAILING	ADDRESS.		CITY	POOL TYPE	: 1	ELE	lc1	l ph	
	•			P00 1		3606	1.0	7. 12	
THE MARKED ITEMS REPRESENT HEALTH CODE VIOLATIONS AND MUST BE CORRECTED AS FOLLOWS:									
□ i.	Provide a readily accessible life ring with an		Replace broken / unreadable depth m	arker tiles.	☐ 4:	. Repair / repla	ce the recirculation	n pump.	
	attached rope of sufficient length to span the maximum width of the swimming pool.	□ 22.	Replace broken / missing coping.		4	. Repair / repla	ce the filter.		
□ 2.	Provide a readily accessible body hook permanently attached to a pole at least 12 ft. in length.	<u> </u>	Provide adequate skimming action in Raise / lower water level to the mid-	•		 Backwash the Provide / repair 	filter. air / replace the 11	nfluent / effluent	
□ 3.	Post a legible sign stating "Warning - No Life-		skimmer opening.		_	pressure gaug			
	guard On Duty" in letters at least 4" high. In addition, the sign shall state "Children under the	1	Replace broken/missing skimmer strai		i	.*	ir / replace the fl		
	age of 14 should not use pool without an adult in		Replace broken/ missing skimmer weit		l	•	iir / replace auton automatic chlori	+	
۱	attendance".	L 21.	Replace broken / missing skimmer divassembly.	ELICI ASIAC	1 47	operational.	automatic cinori	nator tilled and	
[Post a legible sign with a diagrammatic illustra- tion of artificial respiration procedures.	□ 28.	Limit spa pool water temperature to a of 104°F.	maximum	☐ 50		no direct connecti in system with a s		
l .	Post an emergency telephone number "911". Post a legible sign with the maximum occupant	29 .	Animals are prohibited in the pool	and in the		drainage syste			
ان ا	capacity allowed in the pool in letters at least 4"		pool area.			•	l equipment room	,	
	high. Swimming pools = 1 per 20 sq.ft. of pool surface area. Spa pool = 1 per 10 sq.ft.	□ 30.	Discontinue placing chlorine tablets is skimmer(s).	in the pool	l	nation system.	•		
7.	Post a legible spa pool precaution sign. Consult CCR Title 24, Section 3119B.5 for verbiage.	l	Discontinue use of the floating chlori		53	i. Maintain rest condition.	rooms in a clea	in and sanitary	
□ 8.	Post a legible "No Diving Allowed" sign in	∐ 32.	Secure / replace drain cover with an type which can only be removed with		□ 54	•	ver facilities in a cl	ean and sanitary	
	letters at least 4" high. Every spa pool with an emergency shut-off		Secure / repair / replace stair handral		l - 5	* * * * * * * * * * * * * * * * * * * *	sing rooms in a cl	ean and sanitary	
J X	switch shall have a legible sign stating "Spa" Emergency Shut-Off Switch".	□ 34.	Secure / repair / replace ladder/ treads / grab rails at deep end of poo			condition.	s, urinals, wash b		
☐ 10.	All required signs must be clearly visible from	_	Provide / repair or replace underwate	-]]]	ers in good re		251175, 4114 5110W-	
D 11.	the pool deck. Maintain a free chlorine residual of at least 1.0	□ 36.	Maintain underwater pool light(s) "on' times the pool is open for use after de pool is not separately enclosed, mai	ark. If the	1	hot and cold	lavatories shall be water. A means timum of 110°F sh	to limit the hot	
☐ 12.	ppm at all times. Maintain a free chlorine residual of at least 1.5	□ 37.	light(s) on during entire nighttime hor Eliminate deck obstruction.		İ	. Provide soap i	in soap dispensers		
l	ppm when cyanurie acid is used at all times.	l	Eliminate trip and fall hazard of dete	riorating /	l	showers.	in permanently	installed soon	
1	Maintain the pH between 7.2 and 8.0. Maintain the level of cyanuric acid below 100		uplifting decking in pool area. Fill in joint between coping and deck.	expansion	35	dispensers, pa toilet tissue fo	per towels or hot:	air blowers, and	
	ppm.	,	Repair the pool fence enclosure.		☐ 60	. The pool(s) w	as not accessible	or only partially	
	Provide an approved pool water test kit which will measure a free chlorine residual.	☐ 40.	Provide a self-closing gate / door to with self-latching hardware at least	pool area 42" above		inspector to m	inspection. Ple	for a complete	
16.	Eliminate cloudiness and maintain pool water in a clean and clear condition.	 	finished grade. Provide a minimum turnover rate a	s follower			the pool and pool tall be under the s		
D 17.	Eliminate algae growth in the pool.	J ~1 .	Swimming Pools = 6 hours, Swimm built before October 1982 = 8 hours,	ning Pools	i	person who i	s certified as a lician with this De	Swimming Pool	
□ 18.	Vacuum pool. Eliminate din / leaves / debris in the pool.		= 0.5 hours, Wading Pools = 1 hou		l	. Maintain a log	of the pool operat	ion, disinfection	
☐ 19.	Clean the waterline tiles.	☐ 42.	Operate the pool recirculation system the pool is open for use and longer if		ł	residual, pH a	nd maintenance p	rocedures.	
□_20.	Replace broken / missing pool tiles.		to maintain the water clean and clear.	-	63	. Provide adequ	ate lifeguard serv	ce.	
64. OʻI	64. OTHER Personate Irealester Dool. Observed and place chell worker warms								
perty of Port stell should smouth and while on color									
/	/ //								
	99. Pursuant to section 65545		FIELD OFFICE		RECEIV	ED BY	1	ا ر	
	CCR, THIS POOL IS OFFI- CIALLY CLOSED. This pool		ROMEO LIANA		-	12.00)		
	shall not be placed in operation until all violations have been		(310)419-5344		INSPEC	TED BY	111		
	corrected & upon specific writ- ten approval by this agency.	1	(zwy feles z ch		<u> </u>	pomes,	y pl		
	Call to schedule a reinspection.	<u> </u>			REIN	PECTION ON OF	R AFTER		

MBUSD

F. PRESENTATION/DISCUSSION ITEM

1.b. <u>TITLE:</u> Begg Pool Maintenance Update

BACKGROUND: On December 11, 2006, the County of Los Angeles Department of Health Services performed an inspection of the Begg Pool. The report indicated that the District needs to eliminate trip and fall hazard of deteriorating/uplifting decking in the pool area. The Report also indicated that the plaster covering within the pool should be renovated/replastered due to uneven surfaces and peeling. The Report indicated that the pool shell should be smooth and white in color.

District staff has confirmed that the decking repairs are in the process of being scheduled. The cost of re-plastering the pool shell is estimated to be \$50,000-\$70,000. The City of Manhattan Beach has indicated that they are willing to share in the cost of re-plastering the pool shell. However, at this time, the cost of the school district's share of the work is not budgeted. Due to very limited unencumbered facility funds and/or prohibitions against spending Deferred Maintenance matching funds for pool repairs, District staff is exploring the following options:

- 1. Close the facility until funding can be obtained and the plaster replaced
- 2. Operate the pool on a day-to-day basis (subject to immediate closure should an inspection indicate that the facility be closed).
- Make a request to the City to pay for the needed repairs.

The City and the District use the pool on a daily basis for a variety of school and recreational (including adult programs). Some possible options available in the event that the facility is closed, include cancellation of programs and/or transfer of programs to other facilities.

COST AND BUDGET SOURCE: \$30,000-\$35,000 (school district share) - budget source not determined at this time.

ACTION RECOMMENDED: Board direction only.

PREPARED BY: Gary J. Mortimer, Business Services Consultant

DATE OF BOARD MEETING: February 7, 2007